

SECRET

1100Z 03 APR 63

25X1A

DIRECTOR

[REDACTED]

OPS (1-2-3-4-5-6)

S/C (7)

ROUTINE

TOR: 1241Z 03 APR 63

25X1A

[REDACTED]

25X1A

[REDACTED]

25X1A

[REDACTED] 71168

25X1A

[REDACTED]

[REDACTED] 8870

25X1A

A. GRC-147

B. 355

C. 03 APR 63 7 PLUS 20

D. HEADQUARTERS MISSION

E. (1) CABIN PRESS FLUCTUATED 1500 FT IN AUTO POSITION.

CORRECTIVE ACTION: REPLACE MAG. AMP.

(2) AUTO PILOT OSCILLATED SLIGHTLY IN PITCH.

CORRECTIVE ACTION: PENDING INVESTIGATION.

25X1A (3) [REDACTED] SHUTTER POWER SWITCH FAILED AFTER APPROX 500 FT FILM EXP.

CORRECTIVE ACTION: REPLACE SHUTTER POWER SWITCH.

F. NEGATIVE

G. DC GEN

BRUSH WEAR AND OPN NORMAL. MAX TEMP 90 DEGREES C.

END OF MESSAGE

SECRET